

SERVICE PACK CEREC SW 4.2.4

Update Description

The service pack CEREC SW 4.2.4 updates existing CEREC SW 4.2.0, 4.2.1, and 4.2.3 installations.

The service pack contains the following changes:

- **Fixed "cut forever" effect while using cut tool**
- **Fixed endless calculations of the restoration proposal**
- **Fix that a setup was not possible on an CEREC AC with Omnicam with heater controller directly after booting**
- **Fixed Omnicam scanning performance is slowed down by plug-ins**
- **Factory setting for spacer changed to 120µm (does not apply for updating existing systems)**

An existing CEREC SW 4.2 installation is required for this service pack.

We recommend all CEREC SW 4.2 users to install this service pack.